



SCHEMATIC OF PENDANT ASSEMBLY

SWIVEL PENDANT ASSEMBLY INSTRUCTIONS

1. Thread the tapped half ball on to one end of the pendant tube and lock it firmly in place with one of the square nuts provided.
2. Insert the other end of the pendant tube through the cross bar bracket so that the half ball is inside the hat section of the cross bar bracket.
3. Next insert the same end of the pendant tube through the center hole of the canopy / cover so that the cross bar bracket will be on the inside of the canopy / cover.
4. Thread one of the square locking nuts provided on to the other end of the pendant tube, next screw on the threaded bracket with the flat side against the nut. The threaded tube should extend only a 1/4 inch beyond the bracket. Tightening the square nut against the threaded bracket will lock the direction of the fixture.
5. The Legend Cap will have a large clearance hole and two small threaded holes located in the center of the top surface. Place the threaded flat bracket and pendant tube assembly over the center hole and attach it using the two #8-32 machine screws.
6. Attach the cross bar bracket to the junction box with the #8 machine screws.
7. The threaded half ball groove must be registered on the tab in the cross bar to prevent unwanted rotation of the pendant tube assembly.
8. The canopy cover can now be positioned over and snapped to the cross bar by aligning the slots in the cover over the protruding tabs on the cross bar bracket.
9. The direction of the exit sign housing can be adjusted by loosening then re-tightening the square locking nut on the exit housing end of the pendant tube assembly.